Owners manual Switched Mode DC/DC converter The converter must be mounted securely in a cool, dry location. Connect the negative input leads to the minus CONVERTER terminal on the converter. Attention: A bad minus connection could make the output voltage equal to the input voltage! Then connect the input lead via a fuse to the input terminal. At this point make sure that the output voltage is OK. If it is, you may safely connect the equipment to the output OUT terminal via a fuse. (Fuse value equal to the output current). Attention: The currents can be very high. Always use cables of sufficient diameter! If no input and output fuse are used than warranty is void.